







》》》 PARTS DESCRIPTION

》》》 SAFETY PRECAUTIONS

<p>► TOP (A) Plastic Wind Shield</p>	
<p>► Balance (B) AC adapter Socket (C) Weighing platform - Stainless Steel Pan (D) ZERO key Sets display to zero or Substrates weight of a container (E) UNITS key Changes weighing units Used when calibrating (F) ON/OFF key Turns the balance power on/off (G) Low battery indicator  (H) ZERO indicator  Indicates when the balance zero is correct (I) STABLE indicator  Indicates when the reading is stable</p>	
<p>► BOTTOM (J) Battery compartment Battery compartment cover Batteries Batteries are not included</p>	

All safety messages are identified by the following words "WARNING" and "CAUTION"
These words mean the following:

WARNING

Important information to alert you to a situation that might cause serious injury and damage to your property if instructions are not followed.

CAUTION

Important information that tells how to prevent damage to equipment.

When using the balance, the following safety precautions should always be followed.

WARNING

Use the AC adapter designed by the manufacturer for the balance. Other adapters may cause damage to the balance.

CAUTION

Avoid installing the balance in direct sunlight, this may cause poor performance or malfunctions.

Do not mix the type of batteries. Replace all the batteries at the same time.
If the balance is not be used for a long period of time, remove all batteries from the battery compartment to avoid leakage which may cause damage to the instrument.

Avoid overloading or dropping or dropping material onto the platform as that could cause damage to the balance.

Do not spill liquids on the balance as it is not water-resistant. Liquids may damage the case, or if it gets inside of the balance the electronics can be damaged.

Material that has a static electric charge could influence the weighing.
Discharge the static electricity on the samples if possible. Another solution to the problem is to wipe both sides of the pan and the top of the case with an anti-static agent.

Distributed By:



HCL Asia Ltd.

Unit 14, 6/F., Worldwide Industrial Centre,
43-47 Shan Mei Street, Fotan, Shatin, Hong Kong
T: +852 27420018 F: +852 27420053
info@hcl-asia.com.hk

www.hcl-asia.com.hk

>>> SPECIFICATIONS

Built-in four display units	g, g/m ² , oz, oz/yd ²
Max. Capacity	200 g x 0.01g, 20,000 g/m ² x 1 g/m ² , 7 oz x 0.0005 oz, 590 oz/yd ² x 0.05 oz/yd ²
Platform Size	Diameter 100mm (Round)
Completed With	Plastic Wind Shield.
Power Supply	12VAC 150mA Adapter or 6 x AA Batteries

>>> PREPARATION

1. Installing batteries/Connecting the AC adapter

I 、 6x AA size Dry batteries (batteries are not included)

Remove the battery compartment cover and insert six batteries AA size into the battery compartment taking extreme care.

II 、 AC adapter

Plug the AC adapter to the AC adapter socket on the side. The AC input requirement could be 110 or 220Volts (50/60Hz) depending on the area where used, so please verify that.

2. Setting up the balance

CAUTION

Avoid installing the balance in direct sunlight, that may cause poor performance or malfunctions. Place your balance on a firm weighing table so that balance is level. (The balance will not perform accurately when it is not level).

Remove all packing from around the top platform and install the platform.

Place the balance on the firm surface that is flat and level for accurate weighing.

>>> WEIGHING

Before weighing

1. Be aware of the Automatic power-off function.

If the Automatic power-off function is active it may turn the balance off after 2 minutes of inactivity.

2. Error messages

EEEEEE: Overload or EEEELO: AC or / Battery value too low

 Low battery, LO-BAT: Lighted, indicates the power of dry battery is too low

3. Calibration may be required before weighing.

Read "CALIBRATION" first and if necessary, calibrate your balance for accurate weighing

Weighing procedures

1. Press [ON/OFF] to turn on the balance.

When power is turned on, all display segments appear on LCD for a few seconds and finally "0" will appear on the display.

2. Select the weighing unit with [UNITS]

Press [UNITS] to select a weighing unit, g, g/m², oz, oz/yd²


Once the unit has been selected, the weight will be displayed in the selected unit and a symbol for the weight will be shown.

3. Start weighing

I .If you do not use a container for weighing

Verify the reading is **-0-**. If not, press [ZERO] to display **-0-**.

Place the objects on the weighing pan to weigh.


II .When the reading becomes stable, the stable indicator  is displayed.

If you use a container for weighing

Place an empty container on the pan.

Wait for the stability indicator  to be displayed and press [ZERO].

Place the objects to be weighed in the container.

When the reading becomes stable, the stable indicator  is displayed.

Distributed By:



HCL Asia Ltd.

Unit 14, 6/F., Worldwide Industrial Centre,
43-47 Shan Mei Street, Fotan, Shatin, Hong Kong
T: +852 27420018 F: +852 27420053
info@hcl-asia.com.hk

www.hcl-asia.com.hk

»»» CALIBRATION

When to calibrate

- ◆ Calibration may be required when the balance is initially installed.
- ◆ If the balance is moved.
- ◆ With time and use, mechanical deviations may occur.
Therefore calibrate the balance whenever the best accuracy is required or when any deviation is observed when weighing a test weight.

How to calibrate

Before calibrating it is necessary to have the proper calibration weights. The weights should be OIML Class M1 or better.

Capacity	200
Calibration Weight	200g

1. Before entering calibration mode, press [ON/OFF] to turn the power on for 1 minute.

2. Enter calibration mode

Press [ON/OFF] to turn the power off.
Press [UNITS] first, then Press [ON/OFF], while keeping pressing [UNITS], the display will show the A/D value.

3. Calibration

Wait for the stable indicator to be displayed,
Press [UNITS] the display will show "00SAVE", after 2 seconds, the display will return to A/D value.

Place the maximum weight (eg. 200g for 200) on the platform.
After the stable indicator is displayed, then press [UNITS],
The display will show "00SAVE" and now calibration is finished.

4. Press [ON/OFF], turn off the power

Press [ON/OFF] turn on the power again,
Place full weight (eg. 200g for 200) on the platform to make sure whether weighing is correct, if not, repeat steps 2-5.

»»» FUNCTION SETTINGS

1. Enter function setting mode

Pressing [ON/OFF] to return the power off. Press [ZERO] first, then press [ON/OFF], while keeping [ZERO] pressed, the display will show "A-ON", "A-OFF".

2. Selection of auto shut off mode

Press [UNITS] to select auto shut off setting mode (the display will show "A-ON" or "A-OFF").

Press [ZERO] to choose "ON" or "OFF" mode, "ON" means auto shut off function active.

"OFF" means this function inactive.

Turn off power, then turn on power again to enter the normal weighing mode. The delay time will be about 2 minutes.

3. Selection of auto backlight mode

Press [UNITS] to select auto backlight setting mode (the display will show "L-ON" or "L-OFF").

Press [ZERO] to choose "ON" or "OFF" mode, "ON" means auto backlight function active. "OFF" means this function inactive. I.e. Shut off backlight.

Turn off power, then turn on power again to enter the normal weighing mode.

»»» FEATURES

- Auto shut off
- Auto zero tracking
- Auto backlight
- Low battery indication
- g, g/m², oz, oz/yd² conversion
- Large LCD (6 digits 15 mm high)
- Different kinds of pans available
- Net weight/stability indication
- Auto calibration

Distributed By:

HCL Asia Ltd.
Unit 14, 6/F., Worldwide Industrial Centre,
43-47 Shan Mei Street, Fotan, Shatin, Hong Kong
T: +852 27420018 F: +852 27420053
info@hcl-asia.com.hk
www.hcl-asia.com.hk