

Only **1 machine*** is needed
for rivet, eyelet, shank, etc.
see below



2 machines* are needed
for press button, snap, prong, etc.
see below



* it refers to QMAX FT-400 Fully Automatic Snap Attaching Machine